



COMPLAINT ASSESSMENT FORM		
Supplier Name	Budi Karya Sentosa Sejati	Complaint No. : 05/CAF/PCH/II/GAP/2024
Address	Perum Candragaba AP 5 No.26 RT. 27 RW 19 Bahagia Babelan Jawa Barat	
	Bekasi	CIF No.: 001/FIN/II/2024
Phone	021-8583386	
PIC	Budi Santoso	Invoice No. :
PO	PO/23/1987	
Quantity Order		Product : 4 LITER
Quantity Complaint		Specification : SILICON CAIR F148 @LTR
Problem : SILICON CAIR TERLALU KENTAL, sehingga kurang maksimal pada saat penyemprotan di mesin potong .		
Category of Complaint		Claim value (IDR/USD/SGD/EUR) :
☒ Quality		In Words
☐ Packaging		(.....)
☐ Delivery		
☐ Ect		
Data :		
☐ Original sample / before process		☐ Copy of DN
☐ Sample after process		☒ Photo
☐ Comparison sample		☐ Packaging
☐ Inspection Card		☐ Pull Tape (for Picking / Dusting problem)
☐ Ream Label		
☐ Ect		
Notes :		
Jakarta, 28 Februari 2024		
Prepared by, 28-02-2024	Checked by, 28-02-2024	Approved by, 28-02-2024
(Nurul) (Staff Pembelian)	(Maurina Gurning) (Ka. Bag. Pembelian)	(Aris Budi) (Supplier)